1992, 500.

**DOCKET NO.: P04950** 

**CLIENT NO.: NATI15-04950** 

E Customer No.: 23990

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Certificate

**PATENT** 

re U.S. Patent No. :

6,911,868 B1

FEB 1 6 2006

Inventor(s)

Ravi Kumar DVJ

of Correction

Issued

FEB 1 3 2006

June 28, 2005

Title

PHASE-LOCKED LOOP FREQUENCY SYNTHESIZER USING

AUTOMATIC LOOP CONTROL AND METHOD OF OPERATION

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

#### **CERTIFICATE OF MAILING BY FIRST CLASS MAIL**

Sir:

The undersigned hereby certifies that the following documents:

- Request for Certificate of Correction (in duplicate);
- 2. Certificate of Correction (in duplicate); and
- A postcard receipt

relating to the above application, were deposited as "First Class Mail" with the United States Postal Service, addressed to Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on 7, 8, 2006.

Mailer

William A. Munck Reg. No. 39,308

P.O. Drawer 800889 Dallas, Texas 75380 Phone: (972) 628-3600

Fax: (972) 628-3616

E-mail: wmunck@davismunck.com

DOCKET NO.: P04950 PATENT

**CLIENT NO.: NATI15-04950** 

Customer No.: 23990



#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

re U.S. Patent No.:

6,911,868 B1

Inventor(s)

Ravi Kumar DVJ

Issued

June 28, 2005

Title

PHASE-LOCKED LOOP FREQUENCY SYNTHESIZER USING

AUTOMATIC LOOP CONTROL AND METHOD OF

**OPERATION** 

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

# **REQUEST FOR CERTIFICATE OF CORRECTION**

Certain clerical or typographical errors were noted in the above-identified patent as indicated on the attached Certificate of Correction.

Applicant respectfully requests that a Certificate of Correction be issued pursuant to 37 C.F.R. §1.322. It is believed that this error is the office's mistake and therefore no fee is due. If this is incorrect, the Commissioner is hereby authorized to charge any additional fee associated with this communication or credit any overpayment to Deposit Account Number 50-0208.

ATTORNEY DOCKET No.: P04950
PATENT No.: 6,911,868 B1

Respectfully submitted,

DAVIS MUNCK, P.C.

Date: (1827)

William A. Munck

Registration No. 39,308

P.O. Drawer 800889 Dallas, Texas 75380

Telephone: (972) 628-3600 Facsimile: (972) 628-3616

E-mail: wmunck@davismunck.com

### UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,911,868 B1

DATED

: June 28, 2005

INVENTOR(S): Ravi Kumar DVJ

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 10, delete "concurrently herewith" and replace with -- November 6, 2001--;

Column 1, line 13, delete "concurrently herewith" and replace with -- November 6, 2001--;

Column 4, line 24, delete "is";

Column 6, line 48, delete " $1 \le M \le 4.5 \le M \le 9 \le M \le 16$ " and replace with  $-1 \le M \le 4.5 \le M \le 8.9 \le M \le 16$ -.

MAILING ADDRESS OF SENDER:

**Docket Clerk** 

P.O. Drawer 800889

Dallas, Texas 75380

PATENT NO. 6,911,868 B1

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

## (Also Form PTO-1050)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,911,868 B1

DATED

June 28, 2005

INVENTOR(S) :

Ravi Kumar DVJ

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 10, delete "concurrently herewith" and replace with --November 6, 2001--;

Column 1, line 13, delete "concurrently herewith" and replace with --November 6, 2001--;

Column 4, line 24, delete "is";

Column 6, line 48, delete " $1 \le M \le 4.5 \le M \le 9 \le M \le 16$ " and replace with  $-1 \le M \le 4.5 \le M \le 8.9 \le M \le 16$ --.

MAILING ADDRESS OF SENDER:

**Docket Clerk** 

P.O. Drawer 800889

Dallas, Texas 75380

PATENT NO. 6,911,868 B1

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.